# New York State Department of Transportation PIA Safety Flag NB23CTW002

By: Rehan Afridi

Flag Date: May 31, 2023

Superseding Information:

No Flags Superseded

#### Structure Information

BIN: 1065318 Region: 11 - NEW YORK CITY

Feature Carried: 278I278IX2M23027 County: KINGS

Feature Crossed: 6TH AVENUE Political Unit: City of NEW YORK
Orientation: 8 - NORTHWEST Approximate Year Built: 1962

Posted Load Matches Inventory: Yes

Bridge Load Posting (Tons): Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp Number of Spans: 322

#### **Verbal Notification Information**

Person Notified: Muhammad Mubeen Date: May 31, 2023 12:10:00 PM

Of: NYSDOT Region 11

#### Signature Information

Signature: Rehan Afridi, P.E. 075185 Date: May 31, 2023

Reviewed By: Robert Kemp Date: May 31, 2023

Attachments: 5

Flag Date: May 31, 2023

### Flagged Elements

# **No Flagged Elements**

### Flagged Condition Description


This PIA Safety Flag No. NB23CTW002 is a New Flag. Location: Span 97, Pier 97, Column C1 at base.

An electrical cable at the end face of the column base exhibits voltage as tested with a "non-contact voltage detector". The cable is hanging from a junction box attached to the top of the column, and is cut at the lower end with exposed live wires.

This location is within a fenced area (NYSDOT Parking Lot) at 52nd Street and 3rd Avenue.

Flag Date: May 31, 2023

## Flag Photographs




**Attachment Description: Flag Location Plan** 

BIN 1065318

Flag Date: May 31, 2023

Photo Number: 2 Photo Filename: IMG\_1743.JPG



Attachment Description: General view of Flagged Location at Pier 97. Looking Begin.



Attachment Description: Location of Flagged condition at Pier 97, Column C1. Looking Begin.

Attachment Description: The end of the electrical cable is cut with exposed live wires. Looking Begin Right.

Attachment Description: Close-up view of cut electrical cable with exposed live wires. Looking Begin Right.

05/31/20